

# Vlore Combined Cycle Power Plant, Vlore, Albania

On-Site Supervision of quality control and documentation of offshore works for 100 MW CCPP-power plant

Year: 2010 - 2012

Owner: Korporata Elektroenergjitike Shqiptare (KESH) sh.a.

Client: AF-Consult Switzerland Ltd.

## Service:

- Supervision of installation works (launching, sinking) for GRP cooling water pipelines DN 1600 and DN 1800 (offshore) and HDPE chlorination pipe DN 90 (on- and offshore)
- Supervision of sinking of existing oil pipeline DN 18" (on- and offshore), of pigging of the oil pipeline and of new installation of cathodic protection and sacrificial anode of oil pipeline
- Design review and approval of technical documentation, specifications, method statements and drawings (as-trenched, as-laid, as built, drawings in the context of detailed engineering)
- Technical supervision of connecting works of GRP pipeline and additional lamination works
- Technical supervision of hydraulic pressure tests
- Analysis of diver videos

